

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problems Mailbox.**




Fig.1




Fig. 2




Fig.3




Fig.4




Fig. 5




Fig.6




Fig. 7




Fig. 8




Fig. 9




Fig.10




Fig. 11




Fig. 12




Fig.13




Fig.14




Fig. 15




Fig. 16





Fig. 17A






Fig. 18A




Fig. 18B




Fig. 18C




Fig. 19A




Fig.20

UPPER MOTOR SENSOR






Fig. 21A

FIG. 21B






Fig.22






Fig. 23



188

Fig. 24



190




Fig.25




Fig.26





Fig.27


FROM FIG. 27

TO FIG. 28B




LOWER MOTORS
102-2, 4, 6, 8, 10, 12

MINI DRW 7 - 12 MOTORS



REVERSED OUTPUT
CONNECTIONS FOR
LOWER MOTORS

Fig. 28A



UPPER MOTORS
102-1, 3, 5, 7, 9, 11

MINI DRW 1 - 6 MOTORS




Fig. 28B




Fig. 29